

ROCKLER PLAN UPDATE

FILE CABINET PLAN 40477

The updates described herein apply to the version of plan 40477 marked "Rev 10/10".

Update #1: Exploded View, page 1 – proportions incorrect.

The exploded view on page 1 above the Bill of Materials shows the two-drawer cabinet as being deeper from front to back than it is tall, when in fact the cabinet is slightly shallower than it is tall.

Update #2: Exploded View, page 5 – call-outs incorrect.

The call-outs in the exploded view on page 5 are all labeled "4F". The correct call-outs are 3A, 3B, 3C, and 3D as shown.

